THE LAKESIDE VILLAS REVISED REFURB CAPITAL IMPROVEMENTS SCHEDULE FROM 2019 - 2032

The long-term maintenance plan must cover a period of at least 10 years from the date of the last review of the plan

		2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
Current Refurbishing schedule comme													
Villas	13	1	3	3		2	2		2		4	3	3
1 Bed	4							4					
2 Bed	3				_								
itudio	8				7			1					
TOTAL UNITS	28	1	3	3	7	2	2	5	2 E	ternal Painting	4	3	3
New Refurbishing Schedule commenci	ing 2018												
Current Villa Costs													
lefurb costs 2019	40,000												
Refurb costs 2030	45,000	45,000	120,000	120,000		80,000	80,000				180000	135000	135000
1 Bed (4)													
Full refurb	25,000							100,000					
Current Refurb Costs	25,000							100,000					
arrent return costs	23,000												
! Bed (3)													
ull refurb 2019	35,000												
lefurb incl replacing kitchen ber	45,000												
tudio (8)													
ull refurb	25,000												
	25,000				175,000			25000					
OTAL REFURB	I	45,000	120,000	135,000	175,000	90,000	90,000	170,000	80,000	150,000	180000	135000	135000
nnual surplus		164,000	73,132	160,000	160,000	160,000	160,000	160,000	160,000	160,000	160,000	160,000	160,000
pening reserves		107,569	115,735	34,924	39,924	4,924	54,924	104,924	74,924	64,924	69,924	,	,
ther Income		,	,	0-,0	00,02-	-,	·-,·	,	,	2-1,02-1	00,024		
et one-off Levy from Villa Owners													
leek 53		16,000											
dditional Income Generated		.,											
		007.500	400.007	404.004	400.004	404.004	044.004	004.004	004.004	004.004	000.002	400.000	400.000
unds available		287,569	188,867	194,924	199,924	164,924	214,924	264,924	234,924	224,924	229,924	160,000	160,000
verruns Operating expenses		83,834	400.000	425.000	475.000	00.000	00.000	470.000		425.000	400.000	425.000	405.000
roposed Refurb expend		35,000	120,000	135,000	175,000	90,000	90,000	170,000		135,000	180,000	135,000	135,000
illa Window Aluminium Joinery			12,000										
ne Bedroom Double Glazing			21,943										
xterior Painting of Resort		3,000							150,000				
ecurity Cameras		50.000		00.000	00.000	00.000	00.000	00.000	00.000	00.000	00.000	00.000	00.000
apital & Common Property expenses		50,000	24.004	20,000	20,000	20,000	20,000	20,000	20,000	20,000	20,000	20,000	20,000
losing available reserves		115,735	34,924	39,924	4,924	54,924	104,924	74,924	64,924	69,924	29,924	5,000	5,000
dd back minimum reserve		40,000	40,000	40,000	40,000	40,000	40,000	40,000	40,000	40,000	40,000	40,000	40,000
Closing total reserves		155,735	74,924	79,924	44,924	94,924	144,924	114,924	104,924	109,924	69,924	45,000	45,000

Points to Note:

- 1. 1 Villa apartments scheduled to be refurbished 2021 3 Villa apartments in 2022
- 2. The Refurbishing costs are based on historic costs. There may be joinery and bathroom updates as it progresses.
- 3. Common Property Schedule is shown as an ongoing expense on the schedule. This varies greatly from year to year but we allow \$20,000 pa as an average
- 4. The Exterior Painting will be completed 2021/2022 Proposed to be redone 2028
- 5. There is no allowance in the budget for re-roofing or spouting. Historically all spouting maintenance or replacement has been expensed against R & M.
- 6. Replacement of Villa Spa Pools in 2018 All communal spa pools replaced in 2018